

From: [Barth, Edwin](#)
To: [Miller, Gary](#)
Cc: [Timberlake, Dennis](#); [McKernan, John](#)
Subject: some initial comments: San Jacinto River Pits RI
Date: Tuesday, January 22, 2013 2:29:25 PM

pg 3-18 if sediment cap is being evaluated the ground water discharge rate should be measured because most capping transport models use this as a model input parameter

pg 5-109 the dioxin concentration was measured 6 inches above the surface, but burrowing or surface organisms are at the surface interface

Table 1-2 HPAHs are noted what about BAPEq or lower PAHs?

Table 4-3 0% detection frequency is noted for Dioxin/Furan yet min/max/mean conc are provided

Fig 3-5 the Plesistocene Beaumont Formation is represented by two color indices

Edwin F. Barth, Ph.D, P.E., C.I.H., R.S.

Office of Research and Development

U.S. Environmental Protection Agency

26 W. Martin Luther King Drive

Cincinnati, OH 45268

Telephone: (513)-569-7669

Fax: (513)-569-7158

E-mail: barth.ed@epa.gov



9477077